



STEP 1 — TINT WHEEL CALIBRATION (10%–100%)



STEP 2 — NOZZLE LINE CHECK & DENSITY GRADIENT



STEP 3 — SOLID INK COVERAGE BLOCKS (BK / C / M / Y)

